



Service Bulletin

Date:	Affected Models:	Internal or External Use:
7/21/2025	All vehicles	Both

Bulletin Title

Sealing Washers for Fuel Cell

Reason

To prevent fuel leakage from the fuel cell that could possibly lead to safety issues

Action

The M6 bolts that clamp the side plate to the fuel cell will need to be removed and a sealing washer used at each bolt location. The new sealing washer must be between the bolt head and the side plate. The side plate does not need to be removed from the fuel cell.

Note: The fuel cell must be drained before the washers can be installed onto the fuel cell bolts.

Part Replacement

Contact Rush Auto Works for hardware.

If a washer has a tear on the sealing rubber, the washer must be replaced with a non-damaged washer.