



Service Bulletin

Date:

9/12/2025

Affected Models:

Vehicles with Kleinn
Compressors

Internal or External Use:

Both

Bulletin Title

Kleinn Compressor Fuse Replacement

Reason

To avoid blowing a fuse during initial start up

Action

The original 20 amp fuse will need to be replaced with a 30 amp fuse on cars that have a Kleinn compressor.

Part Replacement

The 20 amp fuse will be switched for a 30 amp fuse. Please contact your RUSH Dealer for issues.